





HSF

☐ Packing Notes:

1. Reel : 3000pcs/ Reel.
2. Carton : 51000pcs/ 17 Reel/ Carton.

Pull Out Direction





GATHER MATERIAL DIRECTION

INPUT MATERIAL DIRECTION


END

START




Pull Out Direction

- 1) Seal the carton with tape;
- 2) Attach the label to the side of the carton.



REMARK:

- 1).If there are empty zero boxes, they must be filled with buffer materials.
- 2). Handle with care during handling.
- 3). During transportation, do not stack too much and do not have heavy pressure.
- 4). The upper tape must be flat when sticking the lower tape, and there shall be no bubbles at the sticking place.



PACKING
DRAWING



东莞市溪榜电子有限公司
DONG GUAN XI BANG ELECTRONICS CO., LTD.

GENERAL TOLERANCE X. ±0.20 .XX ±0.15 .XXX ±0.10	DRAWING P. J	TITLE: BATTERY 1.2H 1.6MM PITCH DOUBLE ROW CONNECTOR
APPROVED		P/N: XB-BT42-06CB03-*0
DATE 2022. 07. 15		DRAWING NO. XB-C-BT42-01
ANGEL TOLERANCE X. ±3° .XX ±2° .XXX ±1°	UNIT mm SCALE 1:1 SIZE A4 SHEET 2of2 REV A1	